

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
 Original: OGC, Hobbs, NM 11 11 47 AM '67  
 cc: Regional Office, cc: Partner.  
 cc: file

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Edison "A" WE
9. Well No. 2
10. Field and Pool, or Wildcat Shoe Bar Devonian
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plug and Abandon
2. Name of Operator Sinclair Oil & Gas Company
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-28-67 Pulled tubing and spotted 25 sack cement plug @ 12,456'. Filled hole w/heavy mud, between plugs. Cut 5-1/2"OD casing @ 7700' and pulled. Spot 25 sacks cement plug in top of 5-1/2"OD casing stub @ 7700'. Spot 25 sacks cement plug @ 6222' top of Glorieta. Spot 25 sacks cement plug in 9-5/8"OD casing stub after pulling 335'. 9-5/8"OD casing stub @ 335'. Spot 10 sacks cement plug @ surface, installed regulation plug and abandon marker, cleaned and levelled location. Plug and Abandoned eff: 5-8-67

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 5-10-67

APPROVED BY [Signature] TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: