

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>B-10646-12</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sinclair Oil &amp; Gas Company</b>	8. Farm or Lease Name <b>State-Crambling WN</b>
3. Address of Operator <b>P. O. Box 1920, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>34</b> TOWNSHIP <b>16S</b> RANGE <b>35E</b> NMPM.	10. Field and Pool, or Wildcat <b>Shoe Bar Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 5-103.

**5-7-65 Filled hole w/ heavy mud.**  
**5-8-65 Set C. I. bridge plug @ 12,240' w/2 sacks cement on top from (12,240' to 12,230').**  
**to 5-17-65 Cut off 7"OD 23# N-80 casing @ 5605' and pulled 5605'. Set 25 sacks cement plug in top of 7"OD casing stub at 5605'. Set 25 sacks cement plug at 4987' in bottom of 9-5/8"OD casing and 10 sacks cement plug in cellar and top of 13-3/8"OD casing w/4" x 4' regulation marker, location cleaned and levelled. Plug and Abandon 5-18-65.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <b>FM Singleton</b>	TITLE <b>Senior Engineer</b>	DATE <b>5-19-65</b>
APPROVED BY <b>Leslie A. Clemons</b>	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:  
**Orig:cc: CCC,Hobbs, cc:State Land Office, cc:RFS, cc:file**  
**R.L. McClain**