

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-61

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. Name of Operator  
TOM L. INGRAM  
3. Address of Operator  
P. O. Box 1757, Roswell, NM 88201  
4. Location of Well  
UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM  
THE East LINE, SECTION 35 TOWNSHIP 16S RANGE 35E NMPM.  
15. Elevation (Show whether DF, RT, GR, etc.)  
3961' GR

7. Unit Agreement Name  
8. Farm or Lease Name  
Eidson  
9. Well No.  
1  
10. Field and Pool, or Wildcat  
Wildcat-Atoka  
12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/1/79-11/12/79

Squeezed perfs (6153'-81') w/100 sx Class "C". Drilled out cement to 6213'.  
Perf. 6147, 50, 55, 59, 61, 65. Acidized w/1000 gal 15% NE. Swbd dry.  
Set CIBP @ 6060' w/30' cmt on top.  
Perf 5463, 93, 5501, 11, 21, 39, 5720, 99, 5814, 42, 60, 82, 5924. Acidized perfs  
(5720'-5924') w/1000 gal 15% NE. Swbd dry.  
Set CIBP @ 5700'.  
Acidized perf (5639) w/250 gal MSA.  
Set CIBP @ 5575'.  
Acidized perfs (5463-5521) w/1000 gal 15% NE. Swbd dry.  
Prep to P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maryann P. Cochran TITLE Production Clerk DATE 11/12/79

APPROVED BY Jerry Sexton TITLE Dist. L. Supv. DATE NOV 16 1979  
CONDITIONS OF APPROVAL, IF ANY: