

44-4 XI

HALLIBURTON DIVISION LABORATORY

ANALYTICAL DEPARTMENT
LABORATORY

LABORATORY WATER ANALYSIS

No. W85-245

V. F. Petroleum, Inc.

Date 4/3/85

Seize 580

1 Marionfeld Place

Midland, Texas

This report is the property of Halliburton Company and neither it nor any part thereof nor a copy thereof is to be published or disclosed without first securing the express written approval of laboratory management; it may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Company.

Submitted by _____

Date Rec. 4/1/85

Well No. Cochran Lease

Depth _____

Formation _____

County _____

Field _____

Source _____

	<u>Windmill</u>	<u>House</u>	
Resistivity	<u>13.8 @ 72°F</u>	<u>13.3 @ 72°F</u>	
Specific Gravity	<u>1.002 @ 60°F</u>	<u>1.002 @ 60°F</u>	
pH	<u>7.2</u>	<u>6.8</u>	
Calcium (Ca)	<u>430</u>	<u>430</u>	*MPL
Magnesium (Mg)	<u>N11</u>	<u>N11</u>	
Chlorides (Cl)	<u>260</u>	<u>260</u>	
Sulfates (SO ₄)	<u>N11</u>	<u>N11</u>	
Bicarbonates (HCO ₃)	<u>180</u>	<u>200</u>	
Soluble Iron (Fe)	<u>N11</u>	<u>N11</u>	

Remarks:

*Milligrams per liter

Respectfully submitted,

Analyst: Lee Hisey, Jean Thompson

HALLIBURTON COMPANY

cc:

By _____

CHIEF

NOTICE

THIS REPORT IS LOANED TO THE CUSTOMER SERVICE THROUGH. ANY USE OF THIS REPORT AFTER THAT HALLIBURTON SHALL BE RESPONSIBLE FOR ANY LOSS OR DAMAGE, WHETHER IT BE TO ANY OR OTHERWISE, RESULTING FROM SUCH REPORT OR ITS USE.

RECEIVED
APR 11 1985
HALL OF RECORDS