

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

1969 FEB 1 10 13 AM '69

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-2929</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State BM</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Caudill Devonian</b>
12. County <b>Lea</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>Cities Service Oil Company</b>
3. Address of Operator <b>P. O. Box 69 - Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>K</b> <b>1980</b> FEET FROM THE <b>West</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>16</b> TOWNSHIP <b>15S</b> RANGE <b>36E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3912 DF</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Recompletion in Strawn Formation</b>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 13585, PSTD 13540 - Ran GR-N log. Set C.I. bridge plug @ 13,005' dumped two sx cement on top of C.I. bridge plug. Jet perf. 11515-517 and staged w/100 sx slosset. WOC over-nite, squeezed w/50 sx slosset, displaced 45 sx below tool. Jet perf. 8 holes @ 11425-427' squeezed w/50 sx slosset, displaced 40 sx in formation at max. press. 5600 PSI. Squeeze held ok. Drilled out cement to a new PSTD 11,510. Jet perf. Strawn w/one hole per ft. @ 11,471, 74, 82, 84, 86, 88, 91, 94, 96, & 97; swabbed 219 bbis. water in 36 hrs. Well swabbed dry, acidized w/2000 gals. 15% HCL, max. press 400 PSI @ 4 1/2 bbis. per min. swabbed 48 bbis. water, 0 bbis. oil in 30 hrs. Well kept swabbing dry. Work-over unsuccessful. Well shut in, effective 10-13-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED  
C. D. ROBERTSON

SIGNED \_\_\_\_\_

TITLE **District Office Manager**

DATE **February 7, 1969**

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

1

2

3

4

5

6

7

8

9

10

11