

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>5. State Oil & Gas Lease No. E-529</p>
<p>2. Name of Operator EXXON CORPORATION</p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator P.O. BOX 1600, MIDLAND, TEXAS 79701</p>		<p>8. Farm or Lease Name NEW MEXICO AT STATE</p>
<p>4. Location of Well UNIT LETTER 0, 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 26 TOWNSHIP 15-S RANGE 36-E NMPM.</p>		<p>9. Well No. 1</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3870 DF</p>		<p>10. Field and Pool, or Wildcat DEAN PERMO PENN</p>
<p>12. County LEA</p>		

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU BARBER WELL SERVICE 6-8-73. PULLED RODS AND PUMP. FINISHED PULLING RODS, UNSEAT PKR, LOAD CSC W/MUD, PULL TBC, PKR + BP. SET BP ON WIRELINE @ 10,300'; DUMPED 4' SYS CMT ON TOT. CUT 5 1/2" CSC @ 2160; PULLED OUT HOLE, SPOTTED 50 SX CMT PLUG W/1/2" TBC @ 2211', PULLED TBC OUT OF HOLE. CUT 9 5/8" CSC @ 753' PULLED OUT OF HOLE; SPOTTED 70 SX CMT PLUG @ 803', 100 SX PLUG @ 390' AND 10 SX CMT PLUG @ SURFACE; INSTALLED DIRTY HOLE MARKER, AND CLEAN UP LOCATION. FRW 6-12-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE UNIT HEAD DATE 6-28-73

APPROVED BY *Nathan E. Clegg* TITLE OIL & GAS INSPECTOR DATE FEB 5 1975

CONDITIONS OF APPROVAL, IF ANY: