

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☒ Free ☐
5. State Oil & Gas Lease No. E-2929

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name NEW MEXICO "AP" STATE
3. Address of Operator Box 1600, MIDLAND, TEXAS 79702	9. Well No. 1
4. Location of well UNIT LETTER E, 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 36 TOWNSHIP 15 RANGE 36 N.M.P.M.	10. Field and Pool, or Wildcat DEAN PERMO. PENN
11. Elevation (Show whether DF, RT, GR, etc.) 3854 DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. PULL PRODUCTION EQUIPMENT.
2. SET CIBP AT 11500' w/ 5 SX ON TOP.
3. PERF 5 1/2" OSG FROM 10670-10730'.
4. ACIDIZE AND PLACE ON PUMP.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: D. F. Lince TITLE: SR ADMIN. DATE: 7-10-80

APPROVED BY: [Signature] TITLE: DATE: JUL 16 1980
CONDITIONS OF APPROVAL, IF ANY: