

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-025-03734
<b>1. Type of Well:</b> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> Pronghorn Management Corporation		<b>6. State Oil &amp; Gas Lease No.</b> E9335-S
<b>3. Address of Operator</b> P. O. Box 1772 Hobbs, NM 88241		<b>7. Lease Name or Unit Agreement Name:</b> STATE "T"
<b>4. Well Location</b> Unit Letter <u>M</u> : 2970 feet from the <u>South</u> line and <u>330</u> feet from the <u>West</u> line Section <u>6</u> Township <u>16-S</u> Range <u>36-E</u> NMPM Lea County		<b>8. Well No.</b> 1
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b> 3965' RKB		<b>9. Pool name or Wildcat</b> Townsend Permo Upper Penn

<b>11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</b>	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set CIBP @  $\pm 10,100'$ , Cap with 35' cement
2. Circulate hole with mud laden fluid.
3. Nipple up to  $5\frac{1}{2}"$  casing. Stretch, cut and pull  $\pm 7000'$  csg.
4. Spot cement plug 50' in and out of stub. WOC and tag.
5. Spot 100' cement plug 4680' - 4780'. (Int. csg. shoe) WOC and Tag.
6. Spot 100' cement plug 1939' - 2039'. (Top of salt) WOC and Tag.
7. Spot 10 sx. surface plug.
8. Erect dry hole marker. Clean location.

25 SX OR 100' WHICHEVER IS GREATER  
F/350' to 250' - TAG (13 $\frac{3}{8}$  SHOE)

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G. A. Baber TITLE Partner DATE 4/7/00

Type or print name G. A. BABER Telephone No 505-393-9176  
(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any: