

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO.																				
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER <u>Injection</u>		5. Indicate Type of Lease STATE ☒ FEE ☐																				
2. Name of Operator Greenhill Petroleum Corporation		6. State Oil & Gas Lease No. 87845																				
3. Address of Operator 16010 Barkers Point, Ste., 325, Houston, TX 77079		7. Lease Name or Unit Agreement Name Lovington Paddock Unit																				
4. Well Location Unit Letter <u>0</u> : <u>810</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>16 South</u> Range <u>36 East</u> NMMPM Lea County		8. Well No. 40																				
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		9. Pool name or Wildcat Lovington Paddock																				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data <table border="0"><tr><td colspan="2">NOTICE OF INTENTION TO:</td><td colspan="2">SUBSEQUENT REPORT OF:</td></tr><tr><td>PERFORM REMEDIAL WORK ☐</td><td>PLUG AND ABANDON ☐</td><td>REMEDIAL WORK ☐</td><td>ALTERING CASING ☐</td></tr><tr><td>TEMPORARILY ABANDON ☐</td><td>CHANGE PLANS ☐</td><td>COMMENCE DRILLING OPNS. ☐</td><td>PLUG AND ABANDONMENT ☐</td></tr><tr><td>PULL OR ALTER CASING ☐</td><td></td><td>CASING TEST AND CEMENT JOB ☐</td><td></td></tr><tr><td colspan="2">OTHER: <u>Cleanout and stimulate</u> ☒</td><td colspan="2">OTHER: ☐</td></tr></table>			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐	TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐	PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐		OTHER: <u>Cleanout and stimulate</u> ☒		OTHER: ☐	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																				
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐																			
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐																			
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐																				
OTHER: <u>Cleanout and stimulate</u> ☒		OTHER: ☐																				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.																						

- 1) Spot 200 gal. of 20% NEFE HCL acid in open hole
 - 2) Set pkr. at 5947
 - 3) Pressure test to meet state requirements
 - 4) Stimulate hole with 15 tons of CO₂ and 3000 gal. 20% HCL acid
- 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Michael J. Newport

TITLE

Land Manager-Permian Basin DATE 3-25-91

TYPE OR PRINT NAME

Michael J. Newport

TELEPHONE NO. 955-1146

(This space for State Use)

COPY SENT TO
FOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: