

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRICT	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-7845	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.		8. Farm or Lease Name Lovington Paddock Unit
3. Address of Operator P. O. Box 730, Hobbs, NM 88240		9. Well No. 32
4. Location of Well UNIT LETTER <u>J</u> , <u>1750</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>16S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat Lov. Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3826.6 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Pull tubing and sub pump. TIH w/ 4 3/4" bit and 5 1/2" casing scraper to PBTD 6228'. No Fill. W/bit @ 6200' circ. hole w/ 150 bbl 2% KCL water. Spot 200 gal. 15% NEFE from 6000-6200'. TOH w/tools. TIH w/pkr., set @ 5818'. Load and pressure csg. to 500#. By Western, acidize 5 1/2" csg. perfs 6060-6199 w/5000 gal. 15% NEFE and 800# rock salt in 3 stages. Max. pressure - 3600#, min. pressures - 2000#. Rate - 4 1/2 BPM. Flush w/ 34 bbl KCL water. ISIP - 1900#. 15 min., SI - 1300#. Swab 2 hrs. TOH w/pkr. Run sub pump. Rig down. Before workover - 26 BO, 367 BW. After workover - 33 BO, 334 BW.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W.B. Loh</u>	TITLE <u>District Oper. Mgr.</u>	DATE <u>01/14/86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>JAN 23 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		