NO. OF COPIES RECEIVED	<u>'</u>	Form C-103
DISTRIBUTION	·	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION	COMMISSION Effective 1-1-65
FILE	<u> </u>	
U.S.G.S.		Sa. Indicate Type of Lease
LAND OFFICE		State Fee K
OPERATOR		5. State Oil & Gas Lagse No.
SUND (DO NOT USE THIS FORM FOR PR USE "APPLICA	RY NOTICES AND REPORTS ON WELLS  OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFF TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.	ERENT RESERVOIR.
OIL GAS WELL	OTHER- /,///	7. Unit Agreement Name
2. Name of Operator	<i>wiw</i>	8. Farm or Lease Name 1.17
MObil oil C	orporation	Denton NO. WelFcamp Uni
Bex 633, A	pidland, Texas 79701	3. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
	310 FEET FROM THE NATA LINE AND	
THE EAST LINE, SECT	ION TOWNSHIP RANGE	37-E NMPM.
THITTINITH THE	15. Elevation (Show whether DF, RT, GR,	etc.) 12. County
	3818DF	Lea
16. Check	Appropriate Box To Indicate Nature of N	
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	ORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE	DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST	T AND CEMENT JOB
	OTHER	
OTHER		
17. Describe Proposed or Completed C	operations (Clearly state all pertinent details, and give	pertinent dates, including estimated date of starting any propose
work) SEE RULE 1103.		
Dhigged AND a	bondoned as Pen al	tached Operation Summary
1-107/00	•	/
	. •	
	,	
•		
18. I hereby certify that the informatio	n above is true and complete to the best of my knowled	ge and belief.
V I had II a		11 + 11 + 11
SIGNED W	TITLE AUTHORIS	3ed Hgent DATE 1-14-71
The sal II	Man botton	egat . <u></u>
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF AN	T' U	

JAN 10 1971 JAN 10 1971

RECEIVED

## DAILY DRILLING REPORT

## Denton North Wolfcamp #17-1

- DENTON MORTH WLFC #17-1, Denton North Wlfc Fld, Lea Co, NM. OBJECTIVE: P&A. No AFE Mobil Intr 24.1195% Est Cost to Mobil \$600.
- 12/30/70 12,790 TD, 5½ liner 9506, 8-5/8 csg 4750.
  MIRU X-Pert Well Serv DD unit, SD for nite.
- 12/31/70 Ran Baker DR plug on 2-3/8 tbg set in Baker Model D pkr @ 9320, Howco displ hole w/ mud, spot 5x of cement on DR plug, est top of cement @ 9290, P & LD 42 jts of tbg, SD for nite.
- 1/2/71 Finish P & LD tbg, SD for nite and New Year's.
- Remove csg head, weld onto 5½ csg, remove csg slips, Dia-Log ran free pt indicator, indicated 5½ csg free @ 5250, cut csg @ 5250, P & LD 10 jts of csg, SD for nite & for Sunday.
- 1/5 SD for weather.
- P & LD 5½ csg, total 150 jts and two cut off pieces, total 5250', SD for nite.
- 1/7 Cut flange off 8-5/8 csg, Dia-Log ran free pt indicator, indicated free @ 700, will not pull 8-5/8 csg, ran 2-3/8 tbg OE to 5300, SD for nite.
- 1/8/71 Howco spotted 25x cement 5214-5300, then spotted 25x 4695-4773, P & LD tbg, spotted 10x cement 0-20, inst'l marker, Rel X-Pert Well Serv unit @ 5:00 p.m. 1/7/71. Well P&A 1/7/71. FINAL REPORT.