NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

ional instructions in the Rules		Indicate Nature of Not	ice by Checking B	e10W		
Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon		Notice of Intention to Drill Deeper	ON	
Notice of Intention to Plug Well		Notice of Intention to Plug Back		Notice of Intention to Set Liner	ON	
Notice of Intention to Squeeze		Notice of Intention to Acidize		Notice of Intention to Shoot (Nitro)	ON	
Notice of Intention to Gun Perforate	×	Notice of Intention (Other)	×	Notice of Intention (Other)	on	
OIL CONSERVATION COMP SANTA FE, NEW MEXICO	MISSION	Hobbs ,	Mexico	Арг	-13.1, 1958	
Gentlemen:				. A . B 10 1	3	
Following is a Notice of In		certain work as described			" » 1	itlo
SW 1/4 NF 1/4 of (40-acre Subdivision)	Sec25	, T 143 , R.	.37-E,NMPN	1.,Denton-Wolf	сатр	P
_		·	•		-	
In order to it	FUI (FOLLOW	L DETAILS OF PRO	HE RULES AND	REGULATIONS)	.+. 032601.00	
In order to in	FUI (FOLLOW	L DETAILS OF PRO	HE RULES AND	REGULATIONS) Lowing: Perfora		
In order to in with 4 shots p	FUI (FOLLOW acrease I per foot.	L DETAILS OF PRO INSTRUCTIONS IN TO Production we prop	ne rules and cose the folluting and case	REGULATIONS) Lowing: Perfore sing with 10,000	ga llo ns and	
In order to in with 4 shots p	FUI (FOLLOW acrease I per foot.	L DETAILS OF PROVINSTRUCTIONS IN TO Production we proportion to Acidize down to	ne rules and cose the folluting and case	REGULATIONS) Lowing: Perfore sing with 10,000	ga llo ns and	
In order to in with 4 shots p	FUI (FOLLOW acrease I per foot.	L DETAILS OF PROVINSTRUCTIONS IN TO Production we proportion to Acidize down to	ne rules and cose the folluting and case	REGULATIONS) Lowing: Perfore sing with 10,000	ga llo ns and	
In order to in with 4 shots p	FUI (FOLLOW ACTERS I DET foot.	L DETAILS OF PROVINSTRUCTIONS IN TOPPOSITE PROJECTION WE PROPOSE Acidize down to a cil. Retest well	ne rules and cose the folluting and case	REGULATIONS) Lowing: Perfore sing with 10,000	ga llo ns and	
In order to in with 4 shots p	FUI (FOLLOW ACTERS I DET foot.	L DETAILS OF PROVINSTRUCTIONS IN TOPPOSITE PROJECTION WE PROPOSE Acidize down to a cil. Retest well	Pan American	REGULATIONS) Lowing: Perfore Sing with 10,000 In to production.	ga llo ns and	
In order to in with 4 shots p flush with 200	FUI (FOLLOW ACTERSE I DET foot.	L DETAILS OF PROVINSTRUCTIONS IN TOPPOSITE PROJECTION WE PROPOSE Acidize down to a cil. Retest well	Pan American Position Pield	REGULATIONS) Lowing: Perfore sing with 10,000	gallens and	
In order to in with 4 shots proced	FUI (FOLLOW ACTERSE I DET foot.	L DETAILS OF PROVINSTRUCTIONS IN TOPPOSITE PROJECTION WE PROPOSE Acidize down to a cil. Retest well	Pan American Pan American PositionField Sen	REGULATIONS) Lowing: Perfora Sing with 10,000 In to production. Company or opera Superintendent.	gallons and	