

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lee Whitman "A"
8. Well No. 1
9. Pool name or Wildcat Denton Devonian
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3800' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Hondo Oil & Gas Company
3. Address of Operator P. O. Box 2208, Roswell, NM 88202
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>26</u> Township <u>14S</u> Range <u>37E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/09/88 Set packer @ 11,981'. Tested casing to 500 psi. Swabbed.
8/10/88 Acidized existing Devonian perms. 12,230-12,415' with 20,000 gal. cross-link gelled 15% NEFE Blck. Swabbed well back.
8/17/88 Ran in hole with ESP and set @ 9800'. Hooked up flowline and started pump.
11/25/88 Set CIBP @ 12,335' and dumped 10' cement on top. Set another CIBP @ 12,283' and dumped 10' cement on top.
2/15/89 Acidized Devonian perms. 12,230-12,273' with 2000 gal. 15% NEFE acid.
2/23/89 Acidized Devonian perms. 12,230-12,273' with 1500 gal. 20% CRA + 12,390 gal. gelled brine.
3/01/89 Set tubing anchor @ 9002'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. Z. Butters Jr. TITLE Petroleum Engineer DATE 4/13/89
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 18 1989

APR 18 1969

**OCD
HOBBS OFFICE**