

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-05152
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name: Denton North Wolfcamp Unit Tract 6

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>

8. Well No. 19

2. Name of Operator Stephens & Johnson Operating Co.

9. Pool name or Wildcat Denton Wolfcamp
--

3. Address of Operator P O Box 2249, Wichita Falls, TX 76307-2249
--

4. Well Location Unit Letter <u>K</u> : 1980 feet from the <u>South</u> line and <u>2180</u> feet from the <u>West</u> line Section <u>26 (NE SW)</u> Township <u>14S</u> Range <u>37E</u> NMPM County <u>Lea</u>

10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3825 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well has been temporarily abandoned since 1-1-93. Will plug and abandon.
 See attached plugging procedure.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE Manager of Operations DATE 6-25-02

Type or print name Peyton S. Carnes, Jr. Telephone No. 940-723-2166
 (This space for State use)

APPROVED BY _____ TITLE _____ DATE JUL 30 2002
 Conditions of approval, if any: _____
 GARY W. WINK
 CO. FIELD REPRESENTATIVE


5
L

DENTON NORTH WOLFCAMP UNIT WELL NO. 6-19

Plugging Procedure:

- 1) Set 5 1/2" CIBP @ 9150' with 35' cement on plug.
- 2) Run tubing to 9115', tag plug and load hole with 9.5# mud laden salt water.
- 3) Spot 25 sack plug @ 6300' in 5 1/2" casing.
- 4) Spot 30 sack plug 50' inside of 5 1/2" liner (4649') to 4497' inside of 7 5/8" casing. Tag plug.
- 5) Spot 25 sack plug at 3150' in 7 5/8" casing.
- 6) Spot 25 sack plug at 2200' in 7 5/8" casing.
- 7) Perforate 7 5/8" casing at 490' and circulate to surface with 275 sacks of cement leaving 7 5/8" casing full of cement to surface.
- 8) Cut off casing 3' below ground and install permanent marker.

Denton North Wolfcamp Unit Well No. 6-19
Denton N (Wolfcamp) Field
Lea County, New Mexico



5-1778
1EW