

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A		5. LEASE DESIGNATION AND SERIAL NO. LC 065254	
2. NAME OF OPERATOR Atlantic Richfield Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FWL (Unit letter M)		8. FARM OR LEASE NAME Jones Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3820' DF		10. FIELD AND POOL, OR WILDCAT Denton-Devonian	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, T14S, R37E	
		12. COUNTY OR PARISH Lea	13. STATE N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well has been plugged and abandoned as follows:

Set CIBP @ 12200' and capped w/35' cement. Loaded hole w/gel mud. Shot off and recovered 7" casing from 5800'. Spotted 30 sk cement plug in 7" casing stub @ 5800'. Placed 35 sk cement plug in 9-5/8" casing shoe @ 4678'; placed 35 sk cement inside 9-5/8" casing 2100-2200', and 10 sk cement plug in top of well. Erected dry hole marker. 13-3/8" and 9-5/8" casing strings were cemented to surface and will remain intact. Well P & A 4/11/73. All gel mud contained 25 sx gel/100 barrels of water.

18. I hereby certify that the foregoing is true and correct

SIGNED Ch. L. Litcher

TITLE Dist. Drlg. Supervisor

DATE 5/9/73

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

\*See Instructions on Reverse Side

RECEIVED

NOV 21 1973

OIL CONSERVATION COMM.  
HOUSTON, TEX.