

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name B.C. Dickinson "D"
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201		9. Well No. 6
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>14-S</u> RANGE <u>37-E</u> NMPM.		10. Field and Pool, or Wildcat Denton-Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3816' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been shut in since 1966 when it became uneconomical to produce. No remedial or recompletion possibilities exist and we propose to P & A as shown below.

Load hole w/9#/gal salt gel mud containing 25 sx gel/100 BW.
Set CIBP in 5½" liner at 12075' and cap w/2 sx of cement w/dump bailer.
Set 30 sx cement from 4355-4495' (top of liner @ 4415').
Set 10 sx cement in top of well
Erect dry hole marker, clear & level location.

13-3/8" & 8-5/8" casing strings & 5½" liner will remain intact.

→ Note: CIBP must be capped with minimum of 35' plug

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P.D. Sletcher

TITLE Dist. Drlg. Supervisor

DATE 3/24/72

APPROVED BY John Ryan
Geologist

TITLE _____

DATE MAR 29 1972

CONDITIONS OF APPROVAL, IF ANY: