Orig: & ec: OCC ec: FHR JTR

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WEELS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days affer the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of the commission, within 10 days affer the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of the commission of the Commission. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of Re	port by Checking Be	low		
REPORT ON E Drilling op		REPORT ON REST	ULT OF TEST	REPORT C		
REPORT ON I		REPORT ON RECO	OMPLETION	REPORT C	ON	
		(Date	February 11, 1	1955	Hebbs, New Mexico	•
Following i	s a report on the work do	one and the results obtained	d under the heading n	noted above at the	:	
Sinels	dr ^U il & Gas Com	any		W. T. Mann	*Ba	
Carec	(Company or Operator) Drilling Company (Contractor)	(or)		(Lease)		6
г. 14 S _{, R} 3	7 E , NMPM , 1	enton .	Pool.	Lea		County
		!~5 ~55	·			,
	DETAILE	D ACCOUNT OF WORK	DONE AND RESU	LTS OBTAINED		
Spadded 3:	30 PM 2-4-55					
D 312, se to surface	30 PM 2-4-55 t 13 3/8" OD cast	ing © 311 and come 48 hours and tes	nted with 375 ted casing W/5	100# for 1 h	t. Cement circul our before and a	late: Ner
D 312, se to surface	30 PM 2-4-55 t 13 3/8" OD cast	ing © 311 and come	nted with 375 ted casing W/5	100# for 1 h	t. Cement circul our before and a	later
D 312, se to surface	30 PM 2-4-55 t 13 3/8" OD cast	ing © 311 and come 48 hours and tes	nted with 375 ted casing W/5	100# for 1 h	t. Cement circul our before and a	later Iter
D 312, se to surface	30 PM 2-4-55 t 13 3/8" OD cast	ing © 311 and come 48 hours and tes	nted with 375 ted casing W/5	100# for 1 h	t. Cement circul our before and a	later Pter
TD 312, so to surface drilling o	30 PM 2-4-55 t 13 3/8" OD cast	ing @ 311 and come 48 hours and tes lecrease in pressu	nted with 375 ted casing W/5	iOO# for 1 h	t. Cement circul our before and at	later
TD 312, so to surface drilling c	30 PM 2-4-55 et 13 3/8" OD casi e. Let cement set cement plug. Ne d	ing @ 311 and come 48 hours and tes lecrease in pressu	nted with 375 ted casing W/5 re, resumed dr	iOO# for 1 h	Cement circular before and all present (Title)	later
D 312, so to surface drilling 6	30 PN 2-4-55 t 13 3/8" OD casi . Let coment set coment plug. No d H. W.Shaner	ing @ 311 and come 48 hours and tes lecrease in pressu	nted with 375 ted casing W/5 re, resumed dr	eany	Foresan	
D 312, se to surface	30 PN 2-4-55 t 13 3/8" OD casi . Let coment set coment plug. No d H. W.Shaner	ing @ 311 and come 48 hours and tes lecrease in pressu	oted with 375 ted casing W/5 re, resumed dr Other Gas Comp (Company) I hereby certify that to the best of my k	any t the information anowledge.	Foresan (Title)	
D 312, so to surface drilling 6	30 PN 2-4-55 t 13 3/8" OD casi . Let coment set coment plug. No d H. W.Shaner	ing @ 311 and come 48 hours and tes lecrease in pressu	oted with 375 ted casing W/5 re, resumed dr Oil & Gas Comp (Company)	eny t the information anowledge.	Ferenan (Title) given above is true and cor	