## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Regulations of the Commission.  Indicate Nature of Notice by Checking	ng Below	
OTICE OF INTENTION O CHANGE PLANS	Notice of Intention to Temporarily Abandon Well	NOTICE OF INTENTION TO DRILL DEEPER	
Notice of Intention	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
Notice of Intention	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	-
Notice of Intention To Gun Perforate	Notice of Intention (Other) <b>Test Casing</b>	Notice of Intention (Other)	
OIL CONSERVATION COMMISSANTA FE, NEW MEXICO	SION <u>Midland</u> Taxas	Screaber (Date)	29, 1952
Gentlemen:		The Atlantic Refining	Company
Following is a Notice of Inten	tion to do certain work as described below at the	8 i	. <b>X</b>
(Company	or Operator)	Well No. 8	(Unit)
51 1/4 51 1/4 of Sec	or Operator) , T. 15-8 , R. 37-B ,	NMPM., Denton (NOLICEMP)	•
(40-acre Subdivision)		<b>1</b>	
	FULL DETAILS OF PROPOSED PI	AN OF WORK	
	FULL DETAILS OF PROPUSED PI	AN OF WORK	
,	TOTA ON INSTRUCTIONS IN THE RULES	AND REGULATIONS)	
(	FOLLOW INSTRUCTIONS IN THE RULES	AND REGULATIONS)	
	FOLLOW INSTRUCTIONS IN THE RULES	and regulations)	51.36°.
After drilling to 2	168*, we ran 55 jts. of new 36#, ing with 1100 sax coment and the t 8 PM 11-28-52. After waiting	and regulations)  9/8 0.0.  cosing and set it at 216	il.36% surface.
After drilling to 2 We comented the case The plug was down a	168*, we ran 55 jts. of new 36#, ing with 1100 sax coment and the t 8 PM 11-28-52. After waiting	and regulations)  9/8 0.0.  cosing and set it at 216	il.36% surface.
After drilling to 2 We comented the case The plug was down a	168*, we ran 55 jts. of new 36#, ing with 1100 sax coment and the t 8 PM 11-28-52. After waiting	osing and set it at 216 cement returned to the for the cement to harden	surface.
After drilling to 2 We comented the case The plug was down a	168*, we ran 55 jts. of new 36#, ing with 1100 sax coment and the t 8 PM 11-28-52. After waiting	and regulations)  9/8 0.0.  cosing and set it at 216	surface.
After drilling to 2. We comented the cas: The plug was down a casing will be test	168*, we ran 55 jts. of new 36#, ing with 1100 sax coment and the t 8 PM 11-28-52. After waiting	of 0.0.  casing and set it at 216  coment returned to the  for the coment to harder	a, the

The I have

.