

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-05240
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Lea "G" State
8. Well No. 3
9. Pool name or Wildcat Denton - Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3825'
2. Name of Operator Merit Energy Company	
3. Address of Operator 12222 Merit Drive Suite 1500 Dallas, Texas 75251	
4. Well Location Unit Letter <u>I</u> : <u>1980</u> feet from the <u>South</u> line and <u>990</u> feet from the <u>East</u> line Section <u>2</u> Township <u>15S</u> Range <u>37E</u> NMPM County <u>Lea</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/21/99 MIRU. POOH w/rods. Rod box broken. RIH w/O.S. to fish half box looking up. Caught fish. Urseat pump. Pull up to part. SDON.

6/22/99 POH w/rods & pump. Send pump in for restoration & repairs. Stand back all rods & tbgs. SDON.

6/23/99 MIRU WL. RIH w/Gamma Ray log tools. Run strip from 9000' - 9500'. POOH. RIH w/CIBP & set @ 9550'. Dump bail 20' cmt. on top. RIH w/guns. Perforate 9200' - 9205'; 9209' - 9215'; 9224' - 9232'; 9239' - 9241'; 9252' - 9255'; 9258' - 9268'; 9270' - 9274' (2 spf). RIH w/158 jts. 2-7/8" tbgs. & 136 jts. 2-3/8" tbgs. w/SN @ 9099'. 7" Model "R" pkr. @ 9100'. Put well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lynne Moon TITLE Regulatory Analyst DATE 8/13/99

Type or print name Lynne Moon Telephone No. 972-383-6569

(This space for State use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT SUPERVISOR TITLE  DATE

Conditions of approval, if any: