ENERGY AND MIMERALS DEPARTMENT

DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	T	i -

OIL CONSERVATION DIVISION

Form C-103

DISTRIBUTION	P. O. BO)	< 2088	Revised 19-1-78	
BANTA FE	SANTA FE, NEW			
FILE			5a. Indicate Type of Lease	
U.S.O.S.			State X For	
LAND OFFICE			5. State Off & Gas Lease No.	
OPERATOR			5. State Oil & Gds Leasa No.	
			······································	
SUNDR'S EINT SEU TON OOJ	Y NOTICES AND REPORTS ON POSALS TO DRILL OF TO DETPLY OR PLUG B	WELLS ACA TO A DIFFERENT RESERVOIR. H PROPOSALS.)		
1.			7. Unit Agreement Name	
OIL GAS WELL	OTHER-		•	
2. Name of Operator			8. Farm of Lease Name	
Gulf Oil Corporat	tion .		Lea "G" State	
3. Address of Operator			9. Well No.	
P. O. Box 670, Ho	shhe NM 882/0		1	
	7005, NH 00240		10. Field and Pool, or Wildcat	
4. Location of Well				
UNIT LETTER P	560 FEET FROM THE South	LINE AND660 FEET FROM	Denton Devonian	
_		•		
East LINE, SECTION	on 2 TOWNSHIP 15S	RANGE <u> </u>		
	<u></u>		<u> </u>	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
	3790	1' GL	Lea	
16.	Appropriate Box To Indicate N	large of Notice Report of Ot	her Data	
	• • •		T REPORT OF:	
NOTICE OF INTENTION TO: SUBSEQUENT		TREFORT OF.		
PERFORM REMEDIAL WORK	FLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING PLUG AND ABANDONMENT	
TEMPORARILY ABANDON			· ing and againstance.	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB	Leak X	
		OTHER Repair Casing	Leak A	
OTHER				
	(Classia state all accident de	ails and give pertinent dates includin	g estimated date of starting any proposed	
17. Describe Proposed or Completed Op- work) SEE RULE 1703.	erations (Clearly state all pertinent aet	utis, and give perioden water, incomen	P commerce are of commercial may be abased	
wyray see noae				

POH with tubing and packer. Found hole at 5073'. Set RBP at 8527', dump 2 sacks sand on RBP. Set cement retainer at 5017', test tubing 2000#. Cement with 250 sacks flocele and 250 sacks Class "C". Did not obtain squeeze. Flushed cement with BW to clear hole. Establish injection rate. Squeeze 1100%. Drill cement and cement retainer. Test squeeze 500#. Circulate sand off RBP and POH. WIH with packer and tubing, set packer at 12,344'. Return well to pumping. Complete after repairing casing leak 1-3-83.

18. I hereby certify that the information above is true and co	omplete to the bes	t of my knowledge and belief.		
RDPite	TITLE	Area Engineer	6ATE1-6-83	
ORIGINAL COONED BY JERRY SEXTON			•	
DISTRICT 1 SUPR	TITLE		JAN 10 1983	
CONDITIONS OF APPROVAL, IF ANY:				

RECEIVED

JAN 7 1983

HOMES OFFICE