

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.		

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Polaris Production Corp.	8. Farm or Lease Name Pacific Royalty Co.
3. Address of Operator P. O. box 1749 - Midland, Texas 79701	9. Well No. # 2
4. Location of Well UNIT LETTER <u>I</u> <u>1980'</u> FEET FROM THE <u>South</u> LINE AND <u>330'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>15-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Denton Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3813 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon. Propose to set BP at 9300' w/ 3 sax cement on top; Cut 5½" csg. at free point; circulate mud-laden fluid; Spot 100' cement plug at top of 5½" csg. stub; spot 100' cement plug across Abo Fm. (if exposed); Spot 100' cement plug across Glorieta Fm (if exposed); Spot 100' cement plug at bottom of 8 5/8" intermediate; spot 100' cement plug opposite salt section; and spot 10 sax cement cap at top with 4" marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Remyson TITLE President DATE June 2, 197

APPROVED BY John W. Remyson TITLE  DATE

RECEIVED

JUN 4 1975

OIL CONSERVATION COMM.  
HOBBS, N. M.