

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-05300

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Denton

8. Well No.
13

9. Pool name or Wildcat
Denton Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter D : 762 Feet From The West Line and 660 Feet From The North Line
Section 11 Township 15-S Range 37-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3803' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-15-93 - MIRU DDU. NU BOP. Pick up 5-1/2" RBPlug and 5-1/2" Pkr. on 2-7/8" tbg. GIH Testing 2-7/8" to 5000 psi.
7-16-93 - Clean and test collar and pin thds on 100 jts. 2-7/8" tbg. Set RBP-11,970'. Set pkr. 11,955'. Test down hole to 600 psi. PU to 11,764'. Set pkr. Swab perfs. 11,800-11,940'.
7-17-93 - Swab.
7-20-93 - Release pkr. and RBP. PU and set pkr. at 11,975'.
7-22-93 - Acidize perfs. (12,200'-12,100') w/2500 gals 15% acid. Release plug and pkr. PU to 11,980'. RBP and Pkr. at 11,700'.
7-23-93 - Acidize perfs. 11,800'-11,940' w/5,000 gals 15% NeFe.
7-24-93 - Swab. Release pkr. Go down catch RBP. Release plug. COOH w/tools & tbg.
7-26-93 - GIH w/2-7/8" prod. tbg. and sub pump. Hung well on and start pmpg.
7-30-93 - 30 BO; 1,327 BW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE

Supv. Regulatory Affairs

DATE 08-16-93

TYPE OR PRINT NAME

L. M. Sanders

(915)

TELEPHONE NO. 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

AUG 18 1993

CONDITIONS OF APPROVAL, IF ANY: