

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 9 11 42 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1505

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Lovington San Andres Unit
3. Address of Operator	8. Farm or Lease Name
P. O. Box 730 - Hobbs, New Mexico	9. Well No.
4. Location of Well	22
UNIT LETTER "W" , 330 FEET FROM THE South LINE AND 1630 FEET FROM	10. Field and Pool, or Wildcat
THE West LINE, SECTION 31 TOWNSHIP 16-S RANGE 37-E NMPM.	Lovington San Andres
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Unknown	Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Deepening

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Moving in and rigged up workover unit and pulled tubing.
2. Ran drill pipe with bit and drilled to 4917'.
3. Treated down drill pipe into open-hole section 4760-4917' with 500 gallons "HMA" acid.
4. Pulled drill pipe and reran tubing and set at 4894'.
5. Well pumped 3 bbls. of oil and 3 barrels of water in 24 hours.
6. Workover date: May 26 -- June 6, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(ORIGINAL SIGNED) **H. E. Aab**

SIGNED _____ TITLE **District Superintendent** DATE **June 8, 1966**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: