

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05388
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-7879
7. Lease Name or Unit Agreement Name	
State "p"	
8. Well No.	2
9. Pool name or Wildcat	Lovington Paddock

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	8. Well No. 2
4. Well Location Unit Letter L : 1980 Feet From The South Line and 380 Feet From The West Line Section 32 Township 16-S Range 37-E NMMPM Lea County	9. Pool name or Wildcat Lovington Paddock
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3822' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Abandon Paddock Zone <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOCD 24 hrs. prior to commencement of work.
2. MIRUPU. TOH w/ rods and tubing.
3. Tag plug @ 8260' and circulate hole with mud.
4. TIH w/ 5 1/2" CIBP set @ 6100'. Cap with 35' Class "C" Neat cement (4 sxs, 1.32 ft³/sack). Tag plug.
5. Perf 4 squeeze holes at 4400' (Top of Grayburg @ 4407').
6. TIH w/ 5 1/2" Cmt. Retainer set @ 4350'. Pump 500 gal Flowcheck and 75 sxs Class "C" Neat cement into perf's. WOC. Tag plug.
7. Test casing to 500 # for 30 min. Get chart for NMOCD.

This C-103 to amend C-103 sent to NMOCD on 1-23-92

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paul Kautz TITLE Engineer's Assistant DATE 2-24-92
TYPE OR PRINT NAME _____ TELEPHONE NO. 393-7191

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 26 1992

OCD HOBBS OFFICE