

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

MAR 20 1970

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name Rose Hayes
3. Address of Operator P.O. Box 591, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER N 660' FEET FROM THE South LINE AND 1980' FEET FROM THE West LINE, SECTION 35 TOWNSHIP 16 S RANGE 38 E N.M.P.M.	10. Field and Pool, or Wildcat Knowles Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3712' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted 50 sacks cement from 12,354' to 12,137'. Shot 7-5/8" Casing @ 4977', recovered 125 jts for 4992'. Set 40 sack plug 5045' to 4850' and 40 sack plug from 4809' to 4729'. Shot 10-3/4" Casing @ 396'. Recovered 9 jts. 10-3/4" for 400'. Set 25 sack plug from 413' to 388' and 75 sack plug from 310' to 246' - Well plugged and abandoned effective 1-27-70. Cemented 4" dry hole marker at surface on 3-3-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *E. O. DeLoach*

Area Operations Manager  
Amerada Division

DATE 3-23-70

APPROVED BY *John W. Runyan*  
CONDITIONS OF APPROVAL, IF ANY:

TITLE Geologist

DATE JUL 15 1970