Form	9-331
(May	1963)

SHOOT OR ACIDIZE

REPAIR WELL

## UNITED STATES

CHANGE PLANS

SUBMIT IN TRIPLICATE\*

SHOOTING OR ACIDIZING

		Form Budge	approve t Burez	iu N	o. 42 R	14
٠.	LEASE	DESIG	NATION	AND	SERIAL.	N

24.

,5. LEASE	DESIGNATION	AND BERIAL	NO.
LC	029	405 (b	)

May 1963)	DEPARTMENT THE	EINTERIOR verse side) URVEY	LC 029 405 (b)
(I)o not	SUNDRY NOTICES AND RE use this form for proposals to drill or to dec Use "APPLICATION FOR PERMIT	PORTS ON WELLS '	
OIL WELL		R INJECTION W	S. FARM OR LEASE NAME
Cont	inental Oil C	ompany	MCA Unit
Box	WELL (Report location clearly and in accorde	98240	10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF See also spa At surface	FSL + 1980'FE	-/ - Sill 19	MALT. G-SA REPLES  11. SEC., T., B., M., OR BLK. AND SURVEY OF AREA
1980	1FSL + 1980. FE	L OF Section	Sec. 19 T-175, R-321
14. PERMIT NO.	15. ELEVATIONS (S	how whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE  LEA H. M.
16.	Check Appropriate Box To	o Indicate Nature of Notice, Re	
	NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:
TEST WAT	TREAT PULL OR ALTER CASI	marine marine	a a a a a a a a a a a a a a a a a a a

(Other) Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

WORK COMPLETED: WORK STARTED: 9-20-76 SET RBP AT 900 . PULLED INJECTION TBG. WORK DONE: PMPD 11 GEL W/HOWCO PERF 303 '- 04' W/2 JSPF. W/ SAND TO 870 . PWG DOWN TBG, FOLLOWED W/80 SKS CLASS "H" CMT, 2#/SK SALT & DISPLACED W/8.2 BFW. AIR 2 BPM AT 900 PSI. 2% CA CL. DO CMT TO 815 % TAGGED TOC W/BIT AT 763'. FOR BACKFLOW. PAN & SET PKR ON 112 JTS POOH W/RBP. CHECKED FOR BACKFLOW. CHECKED FOR BACKFLOW. 2-3/8" TBG AT 3505", 10-12 PTS TENSION. TESTED FOR HOLE IN RAN & SET RBP AT 3169 '. POOH W/2-3/8" TBG. RESET RBP AT 2800 . FOUND HOLE IN TBG. POOH. 7" CSG. LOCATED LEAK AT TOL. SET RBP INSIDE LINER AT 3290 . COULD NOT DISPLACE. SPOTTED 250 GALS 15% NE-HCL ACID AT 3187 . SPOTTED 15' OF SAND ON RBP AT 3340'. REVERSED ACID TO PIT. SQUEEZED W/100 SKS CLASS "C" CMT. PERF AT 3220' W/4 SHOTS. DISPLACED W/15 BW. AIR 2 BPM AT 2000#. CA CL & 3#/SK SALT. DO CMT INSIDE DO CMT 3135 - 3189 . TOL. CHECKED FOR BACKFLOW. SPOTTED 250 GALS 15% HCL DOWN TBG. LINER TO 3225 . SET 2ND RBP AT 3327 . CH ECK ED CHECKED FOR BACKFLOW. RAN CMT LINED TBG. LAID DOWN WORKSTRING. HELD OK. FOR BACKFLOW.

18. I hereby certify that the foreyoing is true and correct SIGNED Wm Q. Hullerfuld	TITLE ADMIN. Sup	. DATE 5-18-77
(This space for Federal or State office use)  APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	ACCEPTED FOR RECORD
*S	ee Instructions on Reverse Side	U. S. GEOLOGICAL SURVEY

USGS(5), MCA(3), File

RECEIVED

MAY 2 4 1977

CL Copposition of COMM.

19 office of the second se