

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMITTER'S ORIGINAL
Order Instructions on reverse side

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME MCA Unit
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME MCA Unit Bty 1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 103
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 660' FWL - Unit Letter M	10. FIELD AND POOL, OR WILDCAT Maljamar G-SA
14. PERMIT NO. 30-025-08047	15. ELEVATIONS (Show whether DF, RT, GR, etc.) ?
	16. COUNTY OR PARISH Lea
	17. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
(Other) Ref & Trac	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started 2/26/87. MIRU. Set RBP. Release pki & circulate wellbore clean w/160 bbls fresh water & 2% KCl. Spot 1 sk sand on top of RBP. Swab back 100 BW. Correlated CBL log run & perf 3681'-3668' w/1 jspF. Log from 3795'-3550'. Found perfs from 3681'-71' & 3652'-42'. POOH w/veilog. Perf w/1 jspF at 3660'-70'. POOH. Load backside w/10 bbls fresh water w/2% KCl. Hydraulically frac San Andres 7th zone w/17,850 psi of 16-30 Ottawa frac sand & 415 bbls of hydroxypropyl guar gel fluid. Swab back. Set pki at 3580'. Unset pki & spot 2 bbls HCL-NE-FE 15% acid from 3573'-3450'. Dump 1 sk of sand on top of RBP. Perf 3573'-3560' w/1 jspF. Pumped 14 bbls 15% HCL-NE-FE dropping ballsealers every 28 gals for total of 20 ballsealers. Flush w/22 bbls 2% KCl. Swab well. Circ.

18. I hereby certify that the foregoing is true and correct

SIGNED DE FINNEY TITLE Administrative Supervisor DATE August 18, 1987

(This space for agency or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE SOS
AUG 31 1987

*See instructions on Reverse Side

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) Hondo (2) Cities (1) P.O. Box 1000 (1) L.D.

RECEIVED

SEP 8 1967

002
HHSBS OFFICE

MCA Unit No. 103

Pg 2

cut sand off of bridge plug. POCH w/pt & RBP. Ran
producing equipment & place well on production.
Work completed 3/27/37

RECEIVED

SEP 8 1987

OCD
HOBBS OFFICE