

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other Injector	5. Lease Designation and Serial No. LC 029405A
2. Name of Operator Conoco, Inc.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 10 Desta Dr. Ste 100W, Midland, TX 79705	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter "E", 1980' FNL & 460' FWL Sec. 20, T-17S, R-32E	8. Well Name and No. Qty 2 MCA Unit NO. 253
	9. API Well No. 3002508052
	10. Field and Pool, or Exploratory Area Maljamar Grayburg SA
	11. County or Parish, State Lea, NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Alarming Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other Csg Integrity Test	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to perform the following operations in order to prepare this well for temporary abandonment:

1. Pull out of hole with tubing and Otis Interlock pkc set at 3809'.
2. Run in hole with bit & scraper to 4003'.
3. Set 4.5, 9.5# RBP with equalizing valve @ 3995'.
4. Test to 500 PSIG for 30 mins. (Contact Hobbs BLM office 24 hrs prior to test)
5. Circ well with pkc fluid.

*Like Approved
by State*

14. I hereby certify that the foregoing is true and correct

Signed [Signature]	Title Sr. Conservation Coordinator	Date 04-14-92
(This space for Federal or State office use)		
Approved by _____	Title _____	Date 4/30/92
Conditions of approval, if any:		