

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Federal ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injection Well</u>	7. Unit Agreement Name <u>MCA Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>MCA Unit</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>22</u>
4. Location of Well UNIT LETTER <u>BD</u> , <u>660</u> FEET FROM THE <u>north</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>20</u> TOWNSHIP <u>17S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat <u>Maljamar G-SA</u>
15. Elevation (Show whether DF, RT, CR, etc.)	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. POOH w/ Hg & pki. Set cement retainer at 3408'. Pump 250 sxs class "C" cement w/ 15 sxs on top of retained. G-IH w/ perf gun. Shoot perfs at 1000' w/ 4 1/2 pf. G-IH w/ retained at 950'. Pmpd 150 sxs cement. Circ cmt to surface. Close csg valve. Sp. t 250 sxs to surface. Cut off WH. Install dry hole marker on 10/18/88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Administrative Supervisor DATE December 8, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

TITLE DATE

DEC 13 1988

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY: