

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 42-11421

5. LEASE DESIGNATION AND SERIAL NO.

LC-029405(6)

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Water Injection Well</u>	7. UNIT AGREEMENT NAME <u>McA Unit Lys.</u>
2. NAME OF OPERATOR <u>Continental Oil Company</u>	8. FARM OR LEASE NAME <u>McA Unit Lys.</u>
3. ADDRESS OF OPERATOR <u>P.O. Box 460, Hobbs, N.M.</u>	9. WELL NO. <u>65</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1980' FSL + 1980' FFL of Sec. 20, T-17S, R-32E, Lea County, N.M.</u>	10. FIELD AND POOL, OR WILDCAT <u>Malj. G-5A Rep.</u>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 20, T-17S, R-32E</u>
15. ELEVATIONS (Show whether DF, RT, CR, etc.) <u>3999 BL</u>	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>N.M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Deepen 55' & Stimulate ☒
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work Done: On 4-12-71 - Drilled 6 1/4 hole to new TD 4100'. Washed OH w/1000 gals 20% NE retarded acid. Ran Baker tension packer set at 3485' w/12 ft. tension. Placed well back on injection. Work completed 4-17-71.

Test: on 4-18-71 - Injected 550 BW at 45 PSI in 24 hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]TITLE Administrative AssistantDATE 4-19-71

(This space for Federal or State office use)

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY:

USGS(5) MCA(3) File

TITLE _____

ACCEPTED FOR RECORD

APR 20 1971

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

APR 27 1971

OIL CONSERVATION COMM.
ROBBS, W. M.