

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instruction
verse side) re-Form approved:
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME MCA
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME MCA Unit 17, 1
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, NM 88240	9. WELL NO. 63
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' 75L + 1980' 75L of Sec. 20	10. FIELD AND POOL, OR WILDCAT Maj. G. SA Dupuis
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3977' df
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T. 17S, R. 32E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spotted 40 sks class "C" cnt. on bottom. Tagged cnt. at 3766'. Dred.
hard cnt 3766-3970. Set tbg. at 3968' + spotted 20 sks class "C" cnt
w/ 3# salt + 3# sd per sk w/ 2% CaCl₂. Dred. out bridges 3651-
3666 + 3784-3787. Washed cnt. to 3973'. Set OH cnt. rtr at
3893' + cntd OH 3893-3973' w/ 50 sks class "C" cnt w/ 3# salt + 3#
sand per sk + 2% CaCl₂. Rev. out approx 10 sks cnt from
3883' Tagged T.O.C. at 3885'. Set 2 1/8" tbg at 3866 + placed
one production

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Peabody

TITLE

Admin. Supervisor

DATE

7-31-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AUG 6 1973

DATE

GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

USGS-5 FILE

MCA-3