

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Federal ☐ Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Injection</u>	7. Unit Agreement Name <u>MCA Unit</u>
2. Name of Operator <u>Conoco Inc.</u>	8. Farm or Lease Name <u>MCA Unit Bty 1</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	9. Well No. <u>97</u>
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>west</u> LINE, SECTION <u>20</u> TOWNSHIP <u>17S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat <u>Brush Mountain Pool</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work started on 2/23/88. MIRR. Attempt to release pkr. Pull out w/78 jts 2 3/8" Hg - Hg had parted. Fish for several days. Set 4 1/2" pkr at 2716'. Test communication. Test csq. held okay. POOH w/pkr. C/H w/cement retained set at 2523'. Pmpd 300 sxs class "C" w/2% CaCl₂ & 5% Halad 9. Stung out of retained. Left 100' cement on top of retained. Circulate 36 bbls 9# Brine gel to 200' from surface. Shot 4 squeeze holes at 750'. Establish circulation 2 BPM at 250 psi. Pmpd cement, closed csq valve, squeeze 128 sxs cement at 2 BPM at 750 psi maximum pressure. Install P&A marker on 3/25/88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DF FINNEY TITLE Administrative Supervisor DATE 5/26/88

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

FOR RECORD ONLY

MAY 31 1988

RECEIVED
MAY 27 1988
OCD
HOBBS OFFICE

YING BROTH RM