NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico THE CHEME OCC

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered to the sender on which will be given the approval.

	nd Regulations of the Commission.	F		
	Indicate Nature of	Notice by Checking Be	low	
OTICE OF INTENTION O CHANGE PLANS	Notice of Intention Temporarily Abane		Notice of Intention to Drill Deeper	
OTICE OF INTENTION DELUG WELL	Notice of Intentio to Plug Back	N X	Notice of Intention to Set Liner	
otice of Intention Squeeze	Notice of Intentio to Acidize	N	Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Notice of Intention (Other)	N	Notice of Intention (Other)	
IL CONSERVATION COMMI NTA FE, NEW MEXICO	Hobbs, N	lew Mexico	August 4, 1	960
entlemen :		(Place)	(Date)	***************************************
•			W.1./1 0/1 4	_
			cony Mobil Oil Company	
(Company	or Operator)	Lesse	Well No. 1 in	(Unit)
14 of Se	c 9 , T 158 ,	R 36E NMPM	Caudill Wolfcamp	Pool
Les				
	FULL DETAILS OF PR	OPOSED PLAN O	F WORK	
(FOLLOW INSTRUCTIONS IN	THE RULES AND I	FGII ATIONS	
rd 11900'				
PBTD 10680'				
	', Top Cement @ 9340'.			
, , 008 000 (1111)	, 10p demant e 3340 .			
ropose to plue back	& recomplete in the S	en Andres Porme	tion. Propose to spot	150 aka 7
lest over perforation	as 10418-10644'. Snot	50 ske of T	. Neat @ 6000' & cap v	: 130 #KB T.
vdromite. Perforate	6 6000' w/4 holes an	d establish cir	c to surface w/wtr.,	ALTO BELLE OF
-y	/		c to surrace mimer.	x Competit W/
00 sks Incor 8% Gel	W/1.3% by waight of D	1-23 (Dowell) fl	uid lass siditive	Darfareta el
100 sks Incor 8% Gel	w/1.5% by weight of D w/4 SPF @ 5802. 5790.	≻ 23 (Dowell) f l -5779.5765.&	luid loss additive.]	Perforate at
100 sks Incor 8% Gel the following levels	w/4 SPF @ 5802, 5790,	. 5779, 5765, &	luid loss additive.] 5740. Swab to test.	Perforate at
200 sks Incor 8% Gel the following levels	w/1.3% by weight of D w/4 SPF @ 5802, 5790, on-Haulsion Acid & Com	. 5779, 5765, &	luid loss additive.] 5740. Swab to test.	Perforate at
200 sks Incor 8% Gel the following levels	w/4 SPF @ 5802, 5790,	. 5779, 5765, &	luid loss additive.] 5740. Swab to test.	Perforate at
200 sks Incor 8% Gel the following levels	w/4 SPF @ 5802, 5790,	. 5779, 5765, &	luid loss additive. 1 5740. Swab to test.	Perforate a
200 sks Incor 8% Gel the following levels	w/4 SPF @ 5802, 5790, on-Haulsion Acid & Com	. 5779, 5765, &	luid loss additive.] 5740. Swab to test.	Perforate a
100 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No	w/4 SPF @ 5802, 5790,	5779, 5765, & plete.	5740. Swab to test.	Perforate at
the following levels 3000 gals Reg. 15% No	w/4 SPF @ 5802, 5790, on-Haulsion Acid & Com	5779, 5765, & plete.	5740. Swab to test.	Perforate at
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No	w/4 SPF @ 5802, 5790, on-Haulsion Acid & Com	5779, 5765, & plete.	5740. Swab to test.	Perforate at
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No	w/4 SPF @ 5802, 5790, on-Haulsion Acid & Com	5779, 5765, & aplete. Socony Mobil	5740. Swab to test. 1 011 Company, Inc. Company or Operator	Perforate at
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No oproved	w/4 SPF @ 5802, 5790, on-Haulsion Acid & Com	Socony Mobil By District Dist	5740. Swab to test. 1 011 Company, Inc. Company or Operator Extra Superintendent	Perforate and Acidize w/
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No oproved	w/4 SPP @ 5802, 5790, on-Reulsion Acid & Com	Socony Mobil By District Dist	5740. Swab to test. 1 011 Company, Inc. Company or Operator	Perforate at Acidize w/
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No oproved	w/4 SPP @ 5802, 5790, on-Reulsion Acid & Com	Socony Mobil By District Send (5740. Swab to test. 1 011 Company, Inc. Company or Operator Company or Operator Strain Communications regarding well to	Perforate at Acidise w/
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No pproved xcept as follows:	w/4 SPP @ 5802, 5790, on-Reulsion Acid & Com	Socony Mobil By District Send One Name Socony	5740. Swab to test. 1 011 Company, Inc. Company or Operator 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Perforate at Acidize w/
200 sks Incor 8% Gel the following levels 3000 gals Reg. 15% No pproved	w/4 SPP @ 5802, 5790, on-Reulsion Acid & Com	Socony Mobil By District Send One Name Socony	5740. Swab to test. 1 011 Company, Inc. Company or Operator Company or Operator Strain Communications regarding well to	Perforate a Acidise w/