Form 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED		
Budget Bureau No. 1004-013		
 Expires: March 3 1 ,1993		

SUNDRY NOTICES AND REPORTS ON WELLS	LC 029509B
TOTAL TOTAL AND INCHORES ON WELLS	6. If Indian, Allonee or Tribe Name

ការប៉ុន្តែ 🗀

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICA TE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Other Injection	8920003410 8. Well Name and No.
2. Name of Operator Conoco Inc	MCA Unit, Well # 102 9. API Well No. 30-025-12579 10. Field and Pool, or Exploratory Area Maljamar Grayburg/SA
3. Address and Telephone No. 10 DESTA DR. STE. 100W, MIDLAND, TX. 79705-4500 (915) 686-5424	
4. Location of Well (Footage, Sec., T. R. M. or Survey Description)	
660' FSL & 1980' FWL, Sec. 19, T 17S, R 32E, Unit Ltr 'N'	11. County or Parish, State
	Lea
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Repon Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Casing Integrity Test	Change of Plans New Construction Non-Routine Fracrunng Water Shut-Off Conversion to Injection Dispose Water INole: Reponresuits of multiple compition on Wdd
D		Completion or Recompletion Report and Log form.)

13. Describe Proposed or Compieted Operations (Clearly state ail pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to perform a casing integrity test on the well in preparation for requesting temporary abandonment approval. The following procedure will be followed:

- 1. POOH with production equipment.
- 2. Set a plug within 100' of the top perf.
- 3. Notify the BLM 24 hours before pressure tesing casing to 500 psi for 30 minutes.
- 4. RIH with tubing and circulate packer fluid.
- 5. POOH with tubing and fill hole with packer fluid.

When completed, a successful pressure test will be submitted with a reason and a request to temporarily abandon this well

process process and output	PETER	PROVED WESTER 28 1999
14. I hereby certify that the foregoing is true and correct Signed	BUREAU	ESOURCE AR 646 4-15-99
(This space for Federal or State office use) Approved by Conditions of approval if any:	Title	Date

BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its junediction.

