

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co
P 1980
Hou NM 88241

FORM APPROVED
Budget Bureau No 1004-0135
Expires: March 31, 1993

Lease Designation and Serial No

LC-029509A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

MCA Unit

8. Well Name and No

28

9. API Well No

30-025-12707

10. Field and Pool, or Exploratory Area

Maljamar Grayburg/SA

11. County or Parish, State

Lea, N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well



Oil



Gas



Other

2. Name of Operator

Conoco, Inc.

3. Address and Telephone No.

10 Desta Drive Ste. 100W, Midland, Tx. 79705-4500 (915) 686-5424

4. Location of Well (Footage, Sec., T. R. M. or Survey Description)

660' FNL & 1980' FEL
Sec. 21, T-17S, R-32E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION



Notice of Intent



Subsequent Report



Final Abandonment Notice

TYPE OF ACTION



Abandonment



Recompletion



Plugging Back



Casing Repair



Altering Casing



Other

Temporary Abandonment



Change of Plans



New Construction



Non-Routine Fracturing



Water Shut-Off



Conversion to Injection



Dispose Water

Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Approval is requested to extend temporary abandonment for this well for another year. A valid casing integrity test within the last 5 years should be on file.

This request for temporary abandonment extension is based on future potential for reactivation of this well. Two different scenarios that could lead to reactivation are still being studied:

1. An infill drilling program in the MCA Unit.
2. Reorientation of the current waterflood patterns.

Interpretation of 3-D seismic surveys being done across the unit is expected to resolve these two possible scenarios.

RECEIVED
1997 JUL 29 AM 8:17
BUREAU OF LAND MGMT.
ROSWEIL OFFICE

TA APPROVED FOR 12
MAR 25 1998

14. I hereby certify that the foregoing is true and correct.

Signed

Title

Ann E. Ritchie

Regulatory Agent

Date

July 23, 1997

(This space for Federal or State office use)

(ORIG. SCD.) DAVID R. GLASS
Conditions of approval if any:

Title

PETROLEUM ENGINEER

Date

AUG 08 1997

BLM(6)

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side