

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit Bty 3</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>149</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>2600' FNL & 25' FWL - Unit Letter E</i>	10. FIELD AND POOL, OR WILDCAT <i>Malamar-GSA</i>
14. PERMIT NO. <i>30-025-85008</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>27-17S-32E</i>
15. ELEVATIONS (Show whether DP, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 9/15/87. MIRR. POOH w/ hq & pkr. Circ hole clean. Found collapsed csq at 3653'. Drill out gum 3778'-3915'. Clean out & jet wash gum 3924'-4032'. Clean out & jet wash gum 4017'-4070', circ clean. CO & jet wash to 4073'. G 1 H & recover some junk. Set pkr at 3583'. Run spinner survey. DO from 4096'-4204'. Circ clean & log. Spot 35 bbls 15% HCL-NE-FE acid. Rmpd 5 bbl of gel followed by 62 bbls of resin coated slurry. Rmpd 43 bbls resin coated slurry. DO from 3661'-4204'. Circ clean. Underream to 7" from 3837'-4110'. Ran 5 1/2" liner & cement w/ 90 sxs 50/50 Pozmix class "C" cement w/ 1.75% modified Halad 4. Tag TOL at 3326'. Drill out cement & float collar to 4156'. Circ clean. Acidized 4th zone w/ 61 bbls 15% HCL-NE-FE. Perf 4035'-3955'. Set retainer at 3797' & squeeze w/ 175 sxs class "H" cement. DO cmt & retainer. Circ clean. Perf 3955'-4035'. Run producing equipment. Work completed on 11/4/87.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE *Administrative Supervisor*

DATE

July 14, 1988

This space for Federal or State office use)

APPROVAL

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

Peter W. Chester
JUL 27 1988

*See instructions on Reverse Side

Section 2 of the Act makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) OXY (1) FPCO (1) ZLG

RECEIVED
JUL 21 11 49 AM '88
FBI