

PLUGS AND ADAPTERS

Heaving plug—Material

Length

Depth set

Adapters—Material

Size

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
3"	80'	Nitro	120	6-22	3710-3790	
3½"	70'	"	140	6-22	3790-3860	3981'

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
 Cable tools were used from 0 feet to 3995 feet, and from _____ feet to _____ feet

DATES

_____ Put to producing _____ Input well, 19____
 The production for the first 24 hours was _____ barrels of fluid of which _____ % was oil; _____ %
 emulsion; _____ % water; and _____ % sediment. Gravity, °Bé. _____

If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

EMPLOYEES

Charlie Pyatt, Driller Del Walter, Driller
 M. G. Lapsley, Driller _____, Driller

FORMATION RECORD

FROM	TO	TOTAL FEET	FORMATION
0	730	730	Red Beds
730	880	150	Anhydrite
880	925	45	Red Shale
925	962	37	Red Shale Anhydrite 762
962	1885	923	part
1885	3049	1164	Anhydrite
3049	3063	14	Brown Sand
3063	3079	16	Gray Sand
3079	3334	255	Anhydrite
3334	3344	10	Gray Lime
3344	3385	41	Red Rock
3385	3410	25	Brown Lime
3410	3676	266	Gray Lime
3676	3995	319	Lime

(Copy of Sample Analysis by E. E. Kunny attached)

FORMATION RECORD—CONTINUED