

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20592
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	L3392
7. Lease Name or Unit Agreement Name	State 27
8. Well No.	1
9. Pool name or Wildcat	Kemnitz Lower Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4201 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
W. A. Moncrief, Jr.

3. Address of Operator
Moncrief Building, Ninth @ Commerce, FW, TX 76102

4. Well Location
Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line
Section 27 Township 16S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4201 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 10,700 (w/35' cmt on top). Cut 5 1/2 csg @ 8000. Set 45 sx plug from 7950'-8050'. Set 45 sx plug from 4527-4627'. Set 50 sx 365'-465', Set 5 sx 3'-13'.

Casing: 13 3/8 to 415'; Cmt w/370 sx circulated. 9 5/8 to 4577'; Cmt w/2940 sx circulated. 5 1/2 to 13798'; Cmt w/1975 sx TOC 8190'.

Perfs: 13636-13762 11/79
13035-13076

CIBP: 13140 + 35' Cmt 11/79
11060 + 35' Cmt 11/79

11522-696 5/77
10770-10831 11/77

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Holcomb TITLE Agent DATE 4/18/97
TYPE OR PRINT NAME Patsy Holcomb TELEPHONE NO. 817 336-7232

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE MAY 13 1997
CONDITIONS OF APPROVAL, IF ANY: