

March 31, 1989

Production Department Hobbs Division

4-9-17-32

Oil Conservation Division 1000 W. Broadway Hobbs, New Mexico 88240

Attn: Mr. Jerry Sexton

Dear Sir:

The <u>Maljamar Grayburg Unit #33</u> was recently worked on to "Temporarily Abandon" the wellbore and perform a "Casing Integrity Test" as required for Temporarily Abandoned Wells.

Difficulties were encountered in attempting to set the CIBP. The First CIBP would not set and the Second CIBP set prematurely at 331' while tripping in the hole. Several unsuccessful attempts were made to drillout the CIBP @ 331'. Therefore operations were suspended to determine the most feasible approach to remove the CIBP and temporarily abandon this well. (See attachment A)

Operations on the MGU #33 will be resumed again to attempt removing the CIBP, run tubing to 3850' \pm and set cement plugs in the 5 1/2" casing to plug and abandon this well.

If you have any questions concerning this well, please give me a call at (505) 393-4121.

M. E. akin

M. E. Akins Staff Drilling Engineer

MEA/jay 03319/05