

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE, DESIGNATION AND SERIAL NO.
15-000190

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2.

NAME OF OPERATOR **Standard Oil Company of Texas
A Division of California Oil Company**

3.

ADDRESS OF OPERATOR **3610 Avenue B - Snyder, Texas**

4.

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface**Unit N; 130 FWL and 1980 FWL, Section 10
T-176, R-32E**

14.

PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR. 4095

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tras I Federal

9. WELL NO.

8

10. FIELD NAME OR WILDCAT

(Grayburg-San Andres)

11. SEC., T., S., R., OR BLK. AND

Sec. 15, T.17S, R-32E**NE 1/4**

12. COUNTY OR PARISH

Lee

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐**Completion Procedure** ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐**Supplementary Well History** ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Supplementary Well History**Spencer Well #100 P.M. 6-5-65, drilled 11" hole to 305'. Cemented now 8-5/8" 24', SMC casing at 305 with 200 ann. to surface. WOC 10:30 P.M. 6-5-65. After WOC 8 hours tested casing with 1000 psi. No pressure loss in 30 minutes. Drilled 7-7/8" hole to 4183 and logged. Landed now 4 1/2" 11.6 SMC casing at 4183'. Cemented with 550 ann. WOC 3:00 P.M. 6-15-65. After WOC 18 hours, tested casing with 1000 psi. No pressure loss in 30 minutes. Released rig 6:30 P.M. 6-15-65.****Completion Procedure**

1. Run correlation and cement bond log.
2. If bond O.K., perforate interval 3919'-4127'.
3. Run tubing to 4130' and acidize with 2000 gals mud acid with polymer flt.
4. Nipple up tree, sub well in, place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. W. McCants

TITLE

District Engineer

DATE

June 17, 1965

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED**JUN 18 1965***See Instructions on Reverse Side J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.