The Care of the second Page of Texas 79549 Caccine of the second Page of Caccine of Cac				
NEW MEXICO OIL CONSERVATION COLONISSION Separate Cold Cold Cold Cold Cold Cold Cold Cold	NO. OF COPIES RECUIVED			Form C-103
NEW MEXICO DI. CONSERVATION COMMISSION Conservation Conservat			• .	- · • · · · · · · · · · · · · · · · · ·
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES ON TEXAS 79549 SUNDRY NOTICES OF TEXAS 79549 SUNDRY NOTICES ON TEXAS 79549 SUNDRY NOTICES ON TOWN THE NOTICE OF TEXAS 79549 SUNDRY NOTICES ON TOWN THE NOTICE OF TEXAS 79549 SUNDRY NOTICES ON TOWN THE NOTICE OF TEXAS 79549 SUNDRY NOTICES ON TOWN THE NOTICE OF TEXAS 79549 SUNDRY NOTICES ON TOWN THE NOTICE OF TEXAS 79549 SUNDRY NOTICES ON TOWN THE NOTICE OF TEXAS 79549 SUNDRY NOTICE OF TEXAS 79549 SUNDRY NOTICE OF INTENTION TO: THE SUNDRY NOTICE OF INTENTIO		NEW MEXICO OIL CONS	ERVATION COMMISSION	
CORRECTION DESCRIPTION STATES AND REPORTS ON WELLS SUBJECTION TO SUBJECTION TO SUBJECTION SUBJECTION TO SUBJECTION SUBJECTION TO SUBJECT FROM TO SUBJECT TO SUBJE				
SUNDRY NOTICES AND REPORTS ON WILLS TO STATE OF THE PORTS OF			iion	
SUNDRY NOTICES AND REPORTS ON WILLS OF ANY DESCRIPTION OF THE SECOND SECOND STATES ON WILLS OF ANY DESCRIPTION OF THE SECOND S		CORRECTED RE	PORT USU	State Tee.
SUNDRY NOTICES AND REPORTS ON WELLS STATE OF THE SOURCE AND ACCOUNTS AND THE SOURCE STATE OF THE SOURCE AND ACCOUNTS. STATE OF THE SOURCE AND ACCOUNTS AND ACCO				5. State Oil & Gas Lease No.
The first Common The first Co				K-2813
The first Common The first Co	SUN	IDRY NOTICES AND REPORTS ON	WELLS	
Spotted 25 sxs. cement plug at bottom, loaded with mad. 2. Out and recovered 5½ casing at 7500'; spotted 25 sack coment plug. Cott and recovered 5½ casing at 7500'; spotted 25 sack coment plug at bottom, loaded with mad. 2. Out and recovered 5½ casing at 7500'; spotted 25 sack coment plug. Cott and recovered 5½ casing at 1551. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at bottom, loaded with mad. 3. Spotted 25 sack cement plug at 1501'. 4. Spotted 25 sack cement plug at 1501'. 5. Spotted 25 sack cement plug at 1501'. 5. Spotted 25 sack cement plug at 1501'. 5. Spotted 25 sack cement plug at 1501'. 6. Spotted 25 sack cement plug at 1501'. 7. Spotted 25 sack cement plug at 1501'. 8. Spotted 25 sack cem	NOT USE THIS FORM FOR USE "APPL	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG E ECATION FOR PERMIT — (FORM C-101) FOR SUC	H PROPOSALS.)	
State 22 State 27 State	CAS			7. Unit Agreement Name
State 22 **********************************	with well well	OTHER-		P. Form of Log a Name
3. Sported 25 sack cement plug at bottom, loaded with mud. 2. Cut and recovered 5-2" casing at 7500'; sported 25 sack cement plug at bottom, loaded with mud. 2. Cut and recovered 5-2" casing at 150' case of 5-5/3" casing). 3. Spotted 25 sack cement plug at 150' case of 5-5/3" casing). 5. Spotted 25 sack cement plug at 1520'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 8. Spotted 25 sack cement plug at 1520	·		0.03	
3510 Avenue S - Snyder, Texas 79549 4. Location of Well 1. 1980 ************************************		ny of Texas - A Division	of Unevron Oll Co.	
Location of Wolf **Location of Wolf **Location of Wolf **He 1980 **Est From The North Line and 660 **Est From Wolf Carry **The Unit Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The North Line and 660 **Est From Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 **Est From The Wolf Carry **Int Letter H 1980 *Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf Carry **Int Letter H 1980 ***Est From The Wolf		70510		
Delite Little H 1980 rest from the North Line and 660 rest from Burther Molfcard Time Williams of the Line and 660 rest from Molfcard Line and Line				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ABAMDON		7.080 Nonth	660	Burtner Wolfcamp
1. Spotted 25 sack cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug at 6. Spotted 25 sack cement plug at 1520'. 3. Spotted 25 sack cement plug at 1520'. 4. Spotted 25 sack cement plug at 1520'. 5. Spotted 25 sack cement plug at 1520'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 8. Spotted 25 sack cement plug at 1520'. 9. Moved off casing pullers and levelled location. Installed well marker. 1. Spotted 25 sack cement plug at 1520'. 2. Spotted 25 sack cement plug at 1520'. 3. Spotted 25 sack cement plug at 1520'. 4. Spotted 25 sack cement plug at 1520'. 5. Spotted 25 sack cement plug at 1520'. 6. Capped well with 10 sacks cement and steel plate. 1. Spotted 25 sack cement plug at 1520'. 2. Spotted 25 sack cement plug at 1520'. 3. Spotted 25 sack cement plug at 1520'. 4. Spotted 25 sack cement plug at 1520'. 5. Spotted 25 sack cement plug at 1520'. 6. Capped well with 10 sacks cement and steel plate. 6. Capped well with 10 sacks cement and steel plate. 7. Spotted 25 sack cement plug at 1520'. 8. Spotted 25 sack cement plug at 1520'	UNIT LETTER	TOT GIT		
15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea NOTICE OF INTENTION TO: Perform Remedial work Temporability against Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Perform Remedial work Temporability against Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: ALTERNIS CASING Temporability against work Temporability against Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose proposed or complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose proposed or number of the Gloriest at 5860'. 1. Spotted 25 sxx. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack coment plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 10. Lapped well with 10 sacks cement and steel plate. 11. Davidson Virice Lead Drilling Engineer Davidson NATE MADE ALTERNO Complete To the best of my knowledge and belief. NATE MADE ALTERNO COMPLETED TO THE SUBSEQUENT REPORT OF: ALTERNOCE BY ALTERNO COMPLETED TO THE SUBSEQUENT REPORT OF: ALTERNOCE BY ALTERNO COMPLETED TO THE SUBSEQUENT REPORT OF: ALTERNO COMPLETED TO	aast	22 1		
CR 4169.8 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PROFESSION REMEDIAL WORK PRUE AND ABANDON	THE LINE, SE	CTION TOWNSHIP	/~ HANGENMP	
CR 4169.8 Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUS AND ABANDON PLUS AND ABANDON PLUS AND ABANDON CHANGE PLANS COMMENCE DAILLING OPNS. CASING TEST AND CEMENT 'AB 1. Spotted 25 xxx. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 xack cement plug. @ 7500' 3. Spotted 25 xack cement plug at the top of the Glorieva at 5860'. 5. Spotted 25 xack cement plug at the top of the Glorieva at 5860'. 5. Spotted 25 xack cement plug at 1520'. 7. Spotted 25 xack cement plug at Dottom of surface casing at 381'. 6. Spotted 25 xack cement plug at Dottom of Surface casing at 381'. 6. Capped well with 10 sacks cement and steel place. 9. Noved off casing pullers and levelled location. Installed well marker. 10. Installed well marker. APPROVED BY AP	THITTE THE THE TEST OF THE TES	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK TEMPERATURY ABANDON PULL OR ALTER CASING OTHER 1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug at the top of the Glorieta at 5860'. 4. Spotted 25 sack cement plug at 1590' (base of 6-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1590'. 7. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 9. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 1. Spotted 25 sack cement plug at 1520'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Capped well with 10 sacks cement and steel plate. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at bottom of surface casing at 381'. 1. Spotted 25 sack cement plug at				Lea
NOTICE OF INTENTION TO: PEUS AND ABANDON	10. Char	<u> </u>	·····	ther Data
TEMPORANIEV ABANDON PULL OR ALTER CASING 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) ele note 160. 1. Spotted 25 sxs. cement plug at bottom, located with muss. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug. • 7500' 3. Spotted 25 sack cement plug at the top of the Glorieta at 5860'. 4. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 9. Moved off casing pullers and levelled location. Installed well marker. 10. Investy copyl but the information above is true and complete to the best of my knowledge and belief. 11. Spotted 25 sack cement plug at 1520'. 12. Spotted 25 sack cement plug at 1520'. 13. Spotted 25 sack cement plug at 1520'. 14. Spotted 25 sack cement plug at 1520'. 15. Spotted 25 sack cement plug at 1520'. 16. Spotted 27 sack cement plug at 1520'. 17. Spotted 28 sack cement plug at bottom of surface casing at 381'. 18. Spotted 29 sack cement plug at 1520'. 19. Moved off casing pullers and levelled location. Installed well marker.		• •		
TEMPORABILITY ARABON PULL OR ALTER CASING OTHER 17. Discribe Prepaid or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703. 1. Spotted 25 sxx. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sxck coment plug. © 7500' 3. Spotted 25 sack cement plug at the top of the Glorieta at 5860'. 4. Spotted 25 sack cement plug at 1520'. 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 9. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker.	NOTICE OF	THE ENTION TO		
TEMPORABLY ABABOON PULL OR ALTER CASING OTHER 17. Docartice Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rule 1703. 1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug. © 7500' 3. Spotted 25 sack cement plug at the top of the Glorieta at 5860'. 4. Spotted 25 sack cement plug at 1520'. 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 9. Moved off casing pullers and levelled location. Installed well marker. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief. 18. Thereby copy that the information above is true and complete to the best of my knowledge and belief.	DESTRUCTION DEMENTAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOB OTHER 17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposition work) see role [10]. 1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug. © 7500' 3. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1520'. 7. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 10. Installed well marker. 11. Each Drilling Engineer DATE DATE				PLUG AND ABANDONMENT
1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug. © 7500' 3. Spotted 25 sack cement plug at the top of the Glorieta at 5860'. 4. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 8. Spotted 25 sack cement plug at 1520'. 9. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 1. Spotted 25 sack cement plug at 581'. 1. Capped well with 10 sacks cement and steel plate. 1. Spotted 25 sack cement plug at 581'. 1. Capped well with 10 sacks cement and steel plate. 1. Manual Surface casing pullers and levelled location. Installed well marker. 1. Spotted 25 sack cement plug at 581'. 1. Capped well with 10 sacks cement and steel plate. 1. Spotted 25 sack cement plug at 581'. 1. Capped well with 10 sacks cement and steel plate. 1. Spotted 25 sack cement plug at 580'.		CHANGE PLANS		
1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug at the top of the Glorieta at 5860'. 3. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at 1520'. 8. Spotted 25 sack cement plug at 1520'. 9. Moved off casing pullers and levelled location. Installed well marker. 18. I hereby copyl but the information above is true and complete to the best of my knowledge and belief. 19. Maxwalson 10. Darridson 10. Darrid	Polic on Action casing	_	OTHER	
1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug. • 7500' 3. Spotted 25 sack cement plug at the top of the Glorieta at 5860'. 4. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 10. Installed well marker.	OTHER			
1. Spotted 25 sxs. cement plug at bottom, loaded with mud. 2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug. @ 7500' 3. Spotted 25 sack cement plug at the top of the Giorieta at 5860'. 4. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief. 16. I hereby confirms the information above is true and complete to the best of my knowledge and belief.				
2. Cut and recovered 5½" casing at 7500'; spotted 25 sack cement plug at the top of the Glorieta at 5860'. 3. Spotted 25 sack cement plug at 4500' (base of 8-5/8" casing). 5. Cut and recovered 8-5/8" casing at 1581'. 6. Spotted 25 sack cement plug at 1520'. 7. Spotted 25 sack cement plug at bottom of surface casing at 381'. 6. Capped well with 10 sacks cement and steel plate. 9. Moved off casing pullers and levelled location. Installed well marker. 10. ihereby cepty hat the information above is true and complete to the best of my knowledge and belief. Signed Auridson Title Lead Drilling Engineer DATE 2-9-68		a Operations (Greatly state are personally acc	and gree portion areas, morals	,
APPROVED BY John W. Runyan TITLE Total Drilling Engineer DATE 2-9-68	2. Cut and recove 3. Spotted 25 sac 4. Spotted 25 sac 5. Cut and recove 6. Spotted 25 sac 7. Spotted 25 sac 6. Capped well wi	red $5\frac{1}{2}$ " casing at 7500 '; s k cement plug at the top o k cement plug at 4500 ' (bared 8-5/8" casing at 1581 ' k cement plug at 1520 '. k cement plug at bottom of th 10 sacks cement and ste	potted 25 sack cement pf the Glorieta at 5860' se of 8-5/8" casing). 'surface casing at 381' el plate.	•
APPROVED BY John W. Runyan TITLE DATE	is, i hereby carry, that the informa	ation above is true and complete to the best	of my knowledge and belief.	
APPROVED BY John W. Runyan TITLE DATE	BAI / march	lse		·
APPROVED BY John W. Runyan TITLE DATE	SIGNED 3. Davidson	TITLE I.E	ad Drilling Engineer	DATE 2-9-68
APPROVED BY STATE TITLE DATE				
APPROVED BY		. ()		
CONDITIONS OF APPROVAL, IF ANY:	APPROVED BY	· Kunyan TITLE		DATE
	CONDITION OF APPROVAL, IF	ANY:		

ALLIDAVIT ON CEMENTING

STATE OF TEXAS COUNTY OF Scurry ss	Ed 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I, <u>Ralph Burleson</u> , being	
C. E. KNIGHT & CO. in the capacity of Presiden	and that on
the 20th day of December, 1967,	C. E. Knight and Company
rented equipment and personnel to Standard Gil (for the purpose of cementing,
plugging and abandoning string of casing in their well	No. State 22 Woulf !
Lease, Located in Lea County Co	unty, wears. Information provided me by the Cus-
tomer Company, His Agent or Representative, states tha	t the above string of casing was size $5\frac{111}{2}$. $\frac{8}{6}$. $\frac{8}{6}$. $\frac{6}{6}$.
For this cement job, I mixed the following:	•
25 sx. at bottom-localed w	<u>Uh mud</u> Sacks
25 Dic. at 7500'-25 Dic. at	
4500'25 sx, at boxtom of	f 8 5/8"-25 sx. at Sacks surface-10 sx. in top-welded place.
Based upon the above information, according to	my cement tables, I have calculated that the above
volume of cement will fill up an annular height of	
and hole. The work performe	
of said	FIANT Cafel Bullion
	- Adipie Division
DEFORE ME, the undersigned authority, on this d	ay personally appeared
Ralch Burleson, known to r	ne to be the person whose name is subscribed to this
statement; Who, after being duly sworn upon oath sta	tes: That to the best of his knowledge and belief the
facts as recited above are true and correct.	
Given under my hand and seal this 23md day o	Selv Bruder
N	TOTARY, IN AND FOR
(STOMARSE CRATA	Source County, Texas