STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

The state of the s			
DISTRIBUTION	1		
BANTA FE	1		
FILE	1		
U.S.G.S.	1		
LAND OFFICE	1		
OPPRATOR	1		

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA PE	SANTA FE, NE	W MEXICO 87501	Revised 10-1-78
V.S.O.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5, State Oil & Gas Lease No.
611100			E-4199
SUNDR	Y NOTICES AND REPORTS OF PLUG POSALS TO CAILL ON TO CEEPEN OR PLUG ION FOR PERMIT -" IFCAM C-1011 FOR S	N WELLS	
1.	10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	UCH PROPOSALS.)	7. Unit Agreement Name
WELL X WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
GULF OIL CORPORATION 3. Address of Operator		Eddy-Lea State (NCT-A)	
P.O. Box 670, Hobbs,	NIM 99240		9. Well No.
4. Location of Well	Nri 88240		1 10. Field and Pool, or Wildcat
F	1990 North	2210	Undes. San Andres
0417 EE 71EH 1 1	FEET FROM THE NOT LES	LINE AND	FEET FROM Undes. San Andres
THE West LINE, SECTION	N 2 TOWNSHIP 16	S RANGE 32E	
	15. Elevation (Show whether		12. County
		4309' GL	Lea
Check A	Appropriate Box To Indicate		
NOTICE OF IN	TENTION TO:	SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	-	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
17. Describe Proposed or Completed Operark) SEE RULE 1103.	erations (Clearly state all pertinent de	tails, and give pertinent dates,	including estimated date of starting any proposed
charges. Set cmt rtn	Pull tbg. Set CIBP @55	1150'. Perf 5½" cs cmt + 2% CaClo to	abandonment mud. Cap CIBP sg @ 900' w/(4) ½" circulating surf out annulus. Spot
8. I hereby certify that the information a	The second complete to the best	of my knowledge and belief.	
1/2 8.60	s It.	rea Engineer	7 16 70
TORKO	TITLE AL	on publical	BATE 7-16-79
PPROVED BY	Orig. Signed by Jerry Sexton		JUL 17 1979
	Dist 1, Supv.		•