

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)COPY TO U. S. G.
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-057210

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

BAISH "B" Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

MALIAMAR

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28-17-32 NMPM

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRY HOLE RECEIVED

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4032' R. D. B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Physical abandonment of hole completed 2-15-68
Abandoned as follows:

Spotted 20 sq plug @ 9870'. Shot 5 1/2" casing @ 8162, 8010, 7500, 7212, and pulled from 7005. Spotted 25 sq in and cut of stub; 40 sq plug 5350-5250; 25 sq in + out of 8 5/8" casing 4660. Shot 8 5/8" @ 400, 310, and pulled from 185. 25 sq plug in + cut of stub, 20 sq @ surface and erect P + A marker.

Final cleanup and ground restoration shall be made and subsequent report filed.

TD. 13735
8 7/8" CSA 390' (Cement Circ) LEFT IN HOLE
8 7/8" LEFT IN HOLE 185' TO 4660'
5 1/2" " " 7005 TO 10301.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

2-29-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JAN 13 1969

J L GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

O+4 USGS- H

1- NSW

1- SUSP

1- RRY

1- KEWANEE OIL CO.

Box 1859

MIDLAND, TEXAS 79701