

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Arrequy
9. Well No. 1
10. Field and Pool, or Wildcat Morton Wolfcamp
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Union Oil Company of California
3. Address of Operator c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N. M.
4. Location of Well UNIT LETTER <u>B</u> <u>510</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>15-S</u> RANGE <u>34-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4052 G.R.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Propose to spot a 25 sx cement plug from 10,310-10,391'.
2. Propose to spot a 25 sx cement plug at 5½ casing stub at 8000'.
3. Propose to spot a 25 sx cement plug at top of Glorietta at 6175'.
4. Propose to spot a 25 sx cement plug at 8-5/8 casing shoe at 4610'.
5. Propose to spot a 25 sx cement plug at 8-5/8 casing stub at 2500'.
6. Propose to spot a 25 sx cement plug at top of salt at 1950'.
7. Propose to spot a 25 sx cement plug at 11-3/4 casing shoe at 351'.
8. Propose to spot a 10 sx cement plug at surface with marker.
9. Hole will be loaded with mud-laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>Agent</u>	DATE <u>6/8/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT 1</u>	DATE <u>JUN 10 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 9 1971

OIL CONSERVATION COMM.
HOBBS, N. M.