

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
State & Gas Lease No.	X 2797

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>King Resources Company</b>	8. Former Lease Name <b>Shell State No. 1</b>
3. Address of Operator <b>Security Life Building Denver, Colo 80202</b>	9. Well No. <b>No. 1</b>
4. Location of Well UNIT LETTER <b>0</b> <b>495</b> FEET FROM THE <b>south</b> LINE AND <b>1650</b> FEET FROM THE <b>East</b> LINE, SECTION <b>32</b> TOWNSHIP <b>15-S</b> RANGE <b>32-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>N. Anderson Ranch</b>
15. Elevation (Show whether <b>4298 D. F.</b> )	12. County <b>Lea</b>

18. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
ALTERING CASING <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

We have plugged and abandoned this well according to instructions from your office. Since we had a water flow at 2300 feet the 8 5/8" pipe was not pulled and was left in the well. The well was drilled to a total depth of 9900 feet and plugs were put at the following places:  
 25 sx at 9700 feet  
 25 sx at 7550 feet  
 25 sx at 5700 feet  
 25 sx at 3500 feet at base and in the intermediate pipe which was not pulled.  
 15 sx in top of pipe with cemented marker. As soon as the ground has dried out we will level this location and you will be notified so it can be inspected. Attached is a cementing certificate on this work from Dowell.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <i>Leo B. Burdick</i>	TITLE <i>Agent</i>	DATE <i>Dec. 21, 1967</i>
APPROVED BY <i>John W. Runyan</i>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		