

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30.02522669
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	E 7766

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator PENROC OIL CORPORATION

3. Address of Operator P.O. Box 5970, Hobbs, NM 88241

7. Lease Name or Unit Agreement Name
STATE AE

8. Well No. 2 Y

9. Pool name or Wildcat
LOVINGTON ABO

4. Well Location
Unit Letter L : 1420 Feet From The SOUTH Line and 990 Feet From The WEST Line
Section 36 Township 16 S Range 36 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3845 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-18-94
4-24-94
RU to pull submersible pump - couldn't pull. Cut tbg off 10' above the pump @ 8300'. Pulled 4464' of tbg. Couldn't pull any more. Tbg in two. FL 1500' FS. Attempted to screw back in tbg. could not. RU ~~Leaves~~ Pump Truck. Pumped 120 bbl. of produced water on vac. Next day RU derrick & pumped 225 sacks cement. On 4.22.94 tagged TOC @ 3472'. RU bridge cut free 5 1/2" @ 2139'. Pulled & LD 57 jts. of csg. Set 30sx. plug @ 2189-2100. Next a.m. tagged plug @ 2016'. Mixed 40 sx. gel w/ brine. Displace hole. Set 30sx. plug @ 315'. Set 20sx. plug @ surface. Install BH marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Owner DATE 4/24/94
TYPE OR PRINT NAME M. Y. (Merch) Merchant TELEPHONE NO. (505) 397-3590

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE APR 11 1994

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 26 1994

U.S. DEPARTMENT OF
OFFICE