

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBBS OFFICE  
NEW MEXICO OIL CONSERVATION COMMISSION  
JUN 2 11 40 AM '69

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. K-4282	
7. Unit Agreement Name	
8. Farm or Lease Name Humble "X"	
9. Well No. 1	
10. Field and Pool, or Wildcat North Morton	
12. County Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	2. Name of Operator OLEN F. FEATHERSTONE
3. Address of Operator 239 Petroleum Building, Roswell, New Mexico 88201	4. Location of Well UNIT LETTER C, 510 FEET FROM THE North LINE AND 1830 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 15 S. RANGE 35 E. NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4052' GR. 4065' KB.	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Plug back and convert to SWD Well <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SPUD: 8-22-68 COMP: 9-26-68 T.D. 10,488' Measurements from KB. Propose to pull 5-1/2" casing and plug back to base of San Andres at 6090' and convert well to salt water disposal. Will inject into San Andres through tubing set on packer inside 8-5/8" casing at approximately 4400'. San Andres will be open hole from 4511' to 6090'. This well will be used as supplemental capacity to our Union "32" #1 SWD well located in the NW/4 SW/4 Section 32, Township 14 South, Range 35 East. The North Morton underground pipeline system will be extended south and connected to the Humble "X" #1 well.

Propose to plug back as follows:  
25 sack cement plug at T.D. - 10,488' to 10,288'. This will cover perforations 10,456' - 10,458'.  
25 sack cement plug at top of ABO - 8190' if above 5-1/2" stub.  
25 sack cement plug in 5-1/2" stub.  
25 sack cement plug in top Glorieta at 6100'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles W. Hicks</u> (Charles W. Hicks)	TITLE <u>General Manager</u>	DATE <u>May 29, 1969</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		