NO. OF COPIES RECEIVED	Form C-103
	Supersedes Old
	C-102 and C-103
	Effective 1-1-65
	5a. Indicate Type of Lease
U.S.G.S.	State X Fee
OPERATOR	5. State Oil & Gas Lease No.
	К-33
SUNDRY NOTICES AND REPORTS ON WELLS	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	7, Unit Agreement Name
WELL A WELL OTHER-	
2. Name of Operator	8, Farm or Lease Name
Jake L. Hamon	State K-33
3. Address of Operator	9. Well No.
611 Petroleum Building, Midland, Texas 79701	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER N, 554 FEET FROM THE South LINE AND 1983.7	Shoe Bar East Devonian
THE West LINE, SECTION 30 TOWNSHIP 16 S RANGE 36 E	
THE ENE, SECTION TOWNSHIP RANGE	—
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Lea ()///////
¹⁶ , Church Assessment Day To Juliant Nature of Nation Days	
Check Appropriate Box To Indicate Nature of Notice, Repo	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
	· · ·
PERFORM REMEDIAL WORK	
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING L	
OTHER	·······
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	including estimated date of starting any proposed
work) SEE RULE 1103.	
1. Ran tubing open ended to 5748'. Unable to get deeper because	of bad 5支" Csng. Spotted
150 sk Class C cement plug at 5748'. Hole taking some fluid	while cementing.
2. WOC 48 hrs., tagged top of cement at 5664'. Calculated base of cement at 7180' in 52"	
casing.	
3. Spotted 125 sks of Class C cement through tubing set at 5654'. WOC 14 hrs and tagged	
top of cement at 5265'.	
4. Picked up on 52" csng. and csng. pulled free. Pipe pulled from 5265'. Ran tubing,	
tagged cement at 5270' by tubing measurments.	
5. Circulated around with 9.7# brine mud mixed with 25# of salt gel per bbl.	
6. Set cement plugs as following:	
a. 50 sack Class H cement from 5248' back to 5073'	
b. 100 sack Class H cement from 4342' back to 4153'. Ta	gged cement at 4153'. Base of
9 5/8" casing at 4235', plug is 107' below and 82' in	base of 9 5/8" casing.
7. Shot and pulled 9 5/8" casing from 860'.	
8. Set cement plugs as following:	
a. 75 sack Class H cement plug at 930'. Tagged plug at	800'. Plug is in and out of
9 5/8" casing stub.	and the two and and at
b. 100 sack Class H cement plug at 484'. Tagged plug at	31.81 Base of 13 3/8" cang
at 434'. Plug is 50' below and 86' in 13 3/8" casing	
	· •
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
c. 10 sks Class H cement in top of 13 3/8" csng. and set	
Petroleum Engineer	
signed	
OIL & GAS INSI	PECTOR
	DECTOR
CONDITIONS OF APPROVAL, IF ANY:	

