

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. Not available
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG 2552
7. Lease Name or Unit Agreement Name Lowe State
8. Well No. 1
9. Pool name or Wildcat Saunders Permo Upper Penn

10. Elevation (Show whether DF, RKB, RT, GR, etc.) Not available

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator SAGE ENERGY COMPANY
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	4. Well Location Unit Letter <u>L</u> : <u>660</u> Feet From The <u>West</u> Line and <u>1980</u> Feet From The <u>South</u> Line Section <u>10</u> Township <u>15S</u> Range <u>33E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) Not available	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-21 No. 1 Cement retainer set at 5312' with 200 sxs "C" Neat squeeze to 2400#s.
2-22 No. 2 15 sxs "C" 2% CC at 4326'
2-22 No. 3 35 sxs "C" 2% at CC at 3615' and tagged at 3468'
2-22 No. 4 35 sxs "C" 2% CC at 2037'
2-23 No. 5 65 sxs "C" 2% CC at 289' and tagged at 300', 8 5/8" perforated at 405', 15 sxs inside 8 5/8" and 50 sxs outside.
2-23 No. 6 10 sxs "C" 2% CC at 32' to surface. Welded on plate and marker. P&A 2-23-89
(PBSD 10,020', 13 3/8" casing at 355', cemented with 365 sx. 8 5/8" set at 4280' with 700 sxs. 5 1/2" set at 10,199' with 500 sxs. Perforated from 9565' to 9890'. POH with 3550' of 5 1/2".)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frances Holzgraf TITLE Production Clerk DATE March 3, 1989

TYPE OR PRINT NAME Frances Holzgraf TELEPHONE NO. 915 683 5271

(This space for State Use)

OIL & GAS INSPECTOR

APPROVED BY [Signature] TITLE DATE MAR 05 1991

CONDITIONS OF APPROVAL, IF ANY: