

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG 5224

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
McGrath & Smith, Inc.	State 5
3. Address of Operator	9. Well No.
418 Building of Southwest, Midland, Texas 79701	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM	Tulk Penn
THE East LINE, SECTION 5 TOWNSHIP 15-S RANGE 32-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
GL 4336 KB 4350	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.



Spudded 12:00 Noon, 3-15-69, Drld. 17½" hole to 411'. Cmt. 13-3/8"-48#-Csg. at 398' with 400 sx. circ. Plug down 2:30 p.m., 3-17-69. WOC 12 hrs. Tested to 500 psi - OK. Drilled 11" hole to 4050'. Cmt. 8-5/8-24# & 32# - csg. at 3970' with 400 sx. Plug down 7:25 a.m. 3-25-69. Top cmt. 3245' WOC 14 hrs. Tested 8-5/8" csg. to 1000 psi - ok. Drilled 7-7/8" hole to TD 10115 on 4-19-69. Ran logs. Decided to P & A as dry hole. Proposal to P & A as follows:

spot cement plugs as follows:

25 sx. at 10115  
25 sx. at 9790  
25 sx. at 8940  
25 sx. at 7660  
25 sx. at 5310  
25 sx. at 3970  
25 sx. on 8-5/8" stub (at approx. 1200')  
25 sx. at 398'  
10 sx. in top of 13-3/8  
Install Marker

Verbal Permission obtained from John Runyan on April 18, 1969.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Engineer	DATE April 23, 1969
APPROVED BY 	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		